



Penalty Report 6-21-2025



On Track Report

Car number	Division	Driver	Infraction	Penalty
1	Bandolero bandit	McKenzie Ulmet	Contact with 51 causing caution.	Sent To the rear of the field.
53	Blunderbusts	Ralph Corsinii	Caused intentional caution, did not wait for the push truck.	Put a lap down as a penalty.
41	Legend	Joey Braun	Contact with 78 causing caution.	Sent to the rear of the field.
43	Late Model	Ray Minieri	Contact with 99, looked to clean the car out of the way.	Set one car back in the finish as caution did not come out.

Post Tech Report

Car number	Division	Driver	Infraction	Penalty
5	Crate Modified	Joey Braun	Unapproved rocker arms	Disqualification
41	Crate Modified	Terry Stiles	Unapproved camshaft	Disqualification

